

8/16/2017 J8DC4B1K4N7010427

042792

GMC **1992 BOX VAN** **Color WHITE**

Mileage _____ or exceeded Initials _____ Location _____

**DONT NEED
PICTURES**

Doors 2 3 4 Cond: LF Excellent Good Poor No Good
 LR Excellent Good Poor No Good

Electric windows LF RF Electric Trunk Cable Trunk release

RF RR Power Locks Power Seats Title filed Yes NO

Mirror Left Manual Cable Elec Excellent Good Poor No Good

Wheels Alloy How Many _____ Steel Lugs _____ Size _____

Tires Number _____ Excellent Good Poor No Good Size _____

Antenna Manual Electric Radio CD Ignition Key Door Key

Interior Excellent Good Poor No Good Interior color _____

Glass _____

Transmission Automatic Overdrive 4x4 Front Wheel Drive

Manual Three speed Four Speed Five Speed Six Speed

Steering Column Tilt Excellent Good Poor No Good

Cruise on Turn signal Cruise on Str Wheel No Cruise Air Bag Good L R

Fender Left Excellent Good Poor No Good

Hood Excellent Good Poor No Good

Air cond compressor Y Cond. Excellent Good Poor No Good Unk

Engine size/type _____ MFI EFI Turbo TBI Carburetor Diesel

Headlights :L Excellent Good Poor No Good Wiper Motor

R Excellent Good Poor No Good

Turn Lens: L. Excellent Good Poor No Good

R. Excellent Good Poor No Good

Bumper Front Excellent Good Poor No Good

Grill Excellent Good Poor No Good

Fender Right Excellent Good Poor No Good

Alternator Battery Radiator Ladder Rack Spare Tire Donut

Doors Right RF Excellent Good Poor No Good

RR Excellent Good Poor No Good

Hatch Back Yes _____ Excellent Good Poor No Good

Mirror Right Manual Cable Elec Excellent Good Poor No Good

PROCESSOR _____

Battery removed _____ Gas tank removed _____ Fluids drained _____

Trunk, bed or hatch condition Excellent Good Poor No Good

Bumper Rear condition Excellent Good Poor No Good

Tailights L Excellent Good Poor No Good

R Excellent Good Poor No Good Rear Wiper Good

1 Piece Excellent Good Poor No Good